



Pin	Colour	Function*
1	brown	A/STP0 +
2	brown/white	A/STP0 -
3	red	B/DIR0 +
4	red/black	B/DIR0 -
5	orange	A/STP1 +
6	orange/black	A/STP1-
7	yellow	B/DIR1+
8	yellow/black	B/DIR1 -
9	green	A/STP2 +
10	green/black	A/STP2 -
11	blue	B/DIR2 +
12	blue/white	B/DIR2-
13	purple	WDOG -
14	grey	Z/ENO +
15	grey/black	Z/ENO -
16	white	5V Out
17	white/black	0V
18	pink	Z/ENB1 +
19	pink/black	Z/ENB1 -
20	pale blue	5V Out
21	light blue/black	0V
22	light green	Z/ENB2 +
23	light green/black	Z/ENB2 -
24	white/red	5V Out
25	white/blue	0V
26	purple/white	WDOG +

* Function dependant on Axis Type.



QUICK START GUIDE MDR CABLE (FLEXSLICE)

Strip the non connector end of the cable to form flying leads and wire as required



UK | USA | CHINA | INDIA
WWW.TRIOMOTION.COM
THE MOTION SPECIALIST

CAD data Drawings to aid packaging and mounting are available in various formats from the Trio web site. Products should be wired by qualified persons.
Specifications may change without notice. E & OE

Quick Start v2 December 2017